



Figure 1: Mowed lawn on river embankment (Kikuyu grass).



Figure 2: Properties of Molen Close Street (right hand side of watercourse). Note the mowed lawn up to the watercourse.



Figure 3: Main problem area along Erf 21150 & 21151.



Figure 4: Stormwater outlet along Erf 21150.



Figure 5: Area of main concern.



Figure 6: Degraded watercourse full of rubble.



Figure 7: Properties of Molen Close street with mowed Kikuyu lawns encroaching RE/464.