

Appendix C – Site Photographs



Figure 1: Existing R399 bisecting the Study Site – Orientation West



Figure 2: Existing R399 bisecting the Study Site – Orientation East



Figure 3: Disturbed Agricultural Areas with evidence of some limited AIS clearing



Figure 4: Disturbed Agricultural Areas with Invasive Alien Vegetation Present



Figure 5: Existing Access Point from the R399



Figure 6: Aurora - Juno 400Kv Powerline crossing the Property



Figure 7: Secondary Vegetation with scattered AIS



Figure 8: Agriculturally Transformed Areas