



*Figure 1: On-site wetland under rehabilitation (pegs visible where development would have taken place).*





*Figure 2: Demarcated on-site wetland with partial ground cover.*





*Figure 3: Demarcated area along Camphersdrift system outside the existing overhead powerlines that runs along the Camphersdrift system.*





*Figure 4: Area directly adjacent to the Camphersdrift system demarcated and under rehabilitation (existing overhead powerline and King George houses visible on the photo as well).*





*Figure 5: Pegged platforms visible along with top soil stockpiles in the background.*