

**RE/2833 GREAT BRAK RIVER – PHOTOGRAPHS**

Access Road



Existing Stormwater Channel & Swales




Vegetation

Disturbed area previously used as a horse paddock.

Consists mostly of Kikuyu grass.



Fynbos & Thicket Species



# Alien Removal by Hand

