## PHOTO KEY DIAGRAM

**Photo 1:** East-facing view along Main Street approaching parking area. Stonewalling defining a "gateway"

**Photo 2:** North-facing street elevation along Main Street illustrating section of historic stonewalling proposed to be demolished.

**Photo 3:** Street-facing sandstone walling as view from inside the site boundary.

**Photo 4:** NE corner of the site defining the corner of Main and Read Streets.

**Photo 5:** South-facing view along Read Street.

**Photos 6-9 (left-to-right):** Showing generally dilapidated state of less elaborate historic stonewall presently defining the eastern site boundary.

**Photo 10:** West-facing view of eastern site boundary as viewed from Read Street. Existing secondary site entrance/ present entrance to Erf 390 to left of this image.

**Photo 11:** Northwest-facing panoramic view of site showing existing modern house, small section of remaining stonewall to far left of this image. Norfolk pines evident in the foreground.

**Photos 12, 13, 14 (left-to-right):** Remaining section of former historic boundary wall to southern boundary; Modern stairway leading to the beach; North-facing view from the beach showing remnant of former boundary wall on top of historic retention wall (to left) as well as modern retention wall to the right.