PHOTO KEY DIAGRAM

Photo 1: East-facing view along Main Street approaching parking area. Stonewalling defining a "gateway"

Photo 2: North-facing street elevation along Main Street illustrating section of historic stonewalling proposed to be demolished.

Photo 3: Street-facing sandstone walling as view from inside the site boundary.

Photo 4: NE corner of the site defining the corner of Main and Read Streets.

Photo 5: South-facing view along Read Street.

Photos 6-9 (left-to-right): Showing generally dilapidated state of less elaborate historic stonewall presently defining the eastern site boundary.

Photo 10: West-facing view of eastern site boundary as viewed from Read Street. Existing secondary site entrance/ present entrance to Erf 390 to left of this image.

Photo 11: Northwest-facing panoramic view of site showing existing modern house, small section of remaining stonewall to far left of this image. Norfolk pines evident in the foreground.

Photos 12, 13, 14 (left-to-right): Remaining section of former historic boundary wall to southern boundary; Modern stairway leading to the beach; North-facing view from the beach showing remnant of former boundary wall on top of historic retention wall (to left) as well as modern retention wall to the right.